




*Color contoured data indicate relative EM61 response, i.e. significant buried metallic structures. The EM survey was conducted throughout accessible sections of the scan area, as indicated by black borderline.



17 Town Hall Rd, Truro, MA

Client: HRP

Date: 7/9/24

Figure 1

EM61 Survey Results (metallic structures)